# **GRAHAM + SIBBALD**

# Home Report

65 Brock Road Milton Of Leys Inverness IV2 6HH

Date of Valuation: 3<sup>RD</sup> September 2020 AIMS Ref: NC/TM/2020/08/0145

# single survey

# survey report on:

| Property address | 65 Brock Road<br>Milton Of Leys |
|------------------|---------------------------------|
|                  | Inverness                       |
|                  | IV2 6HH                         |

| Customer | XXXXXXXXXXXX |
|----------|--------------|
|          |              |

| Prepared by | Graham + Sibbald, Chartered Surveyors |
|-------------|---------------------------------------|
|-------------|---------------------------------------|

## 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

| <b>5</b>   | TI   |
|--|--|
| Description  | The property comprises a self-contained first floor flat within a two    |
|  | storey semi-detached block of similar apartments.                        |
|  | ,  |
|  |  |
|  |  |
| Accommodation  | The accommodation may be summarised as follows:                          |
|  | <b>'</b>   |
|  | Ground Floor - Private entrance vestibule and stairs leading to          |
|  | ŭ  |
|  | First Floor - Landing, 2 Bedrooms (one with En suite Shower Room),       |
|  | Bathroom, Living Room, Kitchen.  |
|  | Batilloom, Living Room, Ritchen.   |
|  |  |
|  |  |
| Gross internal floor area (m²)   | 78   |
| Gross internal noor area (iii )  | 76   |
|  |  |
|  |  |
| Neighbourhood and leastion The subjects form part of a modern private residential development of |  |
| Neighbourhood and location   | The subjects form part of a modern private residential development of    |
|  | similar style properties located within the Milton of Leys area lying on |
|  | the southern side of Inverness city centre. Immediate surrounding        |

properties comprise dwellings of a generally similar age and type, whilst all main facilities and amenities can be found within relatively

close proximity.

| Age (year built)             | 2017  |  |  |
|------------------------------|---|--|--|
|                              |   |  |  |
| Weather                      | Dry.  |  |  |
|                              |   |  |  |
| Chimney stacks               | None.   |  |  |
|                              |   |  |  |
| Roofing including roof space | The roof is of pitched design and clad with concrete tiles.   |  |  |
|                              | There was access gained to the accessible roof void area via a ceiling hatch within the first floor Hallway. This confirmed the roof to comprise pre-fabricated timber trusses with there being sterling underboarding below the concrete tiles. Fibreglass insulation has been laid between the ceiling joists.    |  |  |
|                              | Sloping roofs were visually inspected with the aid of binoculars where appropriate.   |  |  |
|                              | Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. |  |  |
|                              |   |  |  |
| Rainwater fittings           | The gutters and downpipes are of plastic manufacture.  Visually inspected with the aid of binoculars where appropriate.   |  |  |
|                              |   |  |  |
| Main walls                   | The main outer walls are of modern cavity construction comprising a structural timber frame inner leaf and roughcasted concrete block outerleaf.  |  |  |
|                              | Visually inspected with the aid of binoculars where appropriate.  Foundations and concealed parts were not exposed or inspected.  |  |  |

| Windows, external doors and        | Windows comprise uPVC double glazed units.  |
|------------------------------------|---|
| joinery                            | The external roofline fascias, eaves and soffits are all formed in uPVC.  |
|                                    | The external roomine fascias, eaves and somes are all formed in drvc.   |
|                                    | Internal and external doors were opened and closed where keys   |
|                                    | were available.   |
|                                    | Random windows were opened and closed where possible.   |
|                                    | Doors and windows were not forced open.   |
|                                    |   |
| External decorations               | Visually inspected.   |
|                                    |   |
|                                    |   |
| Conservatories / porches           | Not applicable.   |
|                                    |   |
|                                    |   |
| Communal areas                     | There are areas of communal garden grounds surrounding the block.   |
|                                    |   |
|                                    |   |
|                                    |   |
| Garages and permanent              | We have been informed that there is a timber and felt garden shed   |
| Garages and permanent outbuildings | which we understand is under the ownership of the current occupiers,  |
| •                                  | _   |
| •                                  | which we understand is under the ownership of the current occupiers,  |
| •                                  | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.   |
| outbuildings                       | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.  Visually inspected.  |
| •                                  | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.  Visually inspected.  The surrounding areas of ground are understood to be on a communal  |
| outbuildings                       | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.  Visually inspected.  |
| outbuildings                       | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.  Visually inspected.  The surrounding areas of ground are understood to be on a communal  |
| outbuildings                       | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.  Visually inspected.  The surrounding areas of ground are understood to be on a communal basis.   |
| outbuildings                       | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.  Visually inspected.  The surrounding areas of ground are understood to be on a communal basis.  The boundaries comprise block walling and timber fencing.                      |
| outbuildings                       | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.  Visually inspected.  The surrounding areas of ground are understood to be on a communal basis.  The boundaries comprise block walling and timber fencing.                      |
| outbuildings                       | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.  Visually inspected.  The surrounding areas of ground are understood to be on a communal basis.  The boundaries comprise block walling and timber fencing.                      |
| Outside areas and boundaries       | which we understand is under the ownership of the current occupiers, however is situated on communal grounds.  Visually inspected.  The surrounding areas of ground are understood to be on a communal basis.  The boundaries comprise block walling and timber fencing.  Visually inspected. |

| Internal walls | Internal walls are plasterboard lined.  |
|----------------|---|
|                | Visually inspected from floor level.  |
|                | Using a moisture meter, walls were randomly tested for dampness where considered appropriate. |

| Floors including sub floors | The flooring is of suspended timber construction, although the inspection of floor surface areas was greatly restricted due to the presence of fitted floor coverings.  There were no sub-floor areas available for inspection.  Surfaces of exposed floors were visually inspected. No carpets or |
|-----------------------------|--|
|                             | floor coverings were lifted.  Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.                       |

| Internal joinery and kitchen | Internal skirtings and architraves are of painted timber finish, whilst             |
|------------------------------|---|
| fittings                     | internal doors are of modern timber panel type.                                     |
|                              | The kitchen comprises a range of modern wall mounted cabinets and worktop surfaces. |
|                              | Built-in cupboards were looked into but no stored items were moved.                 |
|                              | Kitchen units were visually inspected excluding appliances.                         |

| Chimney breasts and fireplaces | None.   |
|--------------------------------|---|
|                                |   |
| Internal decorations           | Internal decorations comprise painted finishes. |
|                                | Visually inspected.                             |

| Cellars | Not applicable. |
|---------|-----------------|
|         |                 |

#### **Electricity**

Mains supply. The electrical meter and consumer unit are contained within a cupboard at the ground floor entrance vestibule.

Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards.

#### Gas

Mains supply. There was an external gas meter.

Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards.

# Water, plumbing, bathroom fittings

Mains supply. The visible plumbing installation is in copper and plastic pipework where seen.

The sanitary fittings within the en suite Shower Room and Bathroom are all of modern type.

Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.

#### Heating and hot water

Fixed central heating is provided by a gas fired 'Promax Ultra Combi 40' boiler which is within the Kitchen and this serves a series of water filled radiators. This also provides for domestic hot water on demand.

Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.

| Drainage | Main sewer.                                      |
|----------|--|
|          | Drainage covers etc were not lifted.             |
|          | Neither drains nor drainage systems were tested. |

| Fire, smoke and burglar alarms | Visually inspected. No tests whatsoever were carried out to the |
|--------------------------------|---|
|                                | system or appliances.   |

#### **Additional limits to inspection**

At the date of inspection, the property was occupied and fully furnished whilst all floors were covered.

Not all windows and doors were tested at the time of inspection.

Insulation has been laid over the roof joists and accordingly a head and shoulders inspection of the roof space was possible only.


Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

No inspection for Japanese Knotweed was carried out and unless otherwise stated for the purpose of this report, it is assumed that there is no Japanese Knotweed within the boundaries of the property or neighbouring properties.

### Sectional Diagram showing elements of a typical house



- Chimney pots Coping stone 3 Chimney head 4 Flashing Ridge ventilation 5 Ridge board Slates/tiles 8 Valley guttering 9 Dormer projection 10 Dormer flashing 11 Dormer cheeks 12 Sarking 13 Roof felt 14 Trusses 15 Collar 16 Insulation 17 Parapet gutter 18 Eaves guttering 19 Rainwater downpipe 20 Verge boards / skews 21 Soffit boards 22 Partition wall 23 Lath / plaster 24 Chimney breast
- 28 Brickwork / pointing
  29 Bay window

Window sills

Rendering

Window pointing

projection

30 Lintels

25

26

27

Cavity walls / wall ties

32 Subfloor ventilator

33 Damp proof course

34 Base course

35 Foundations

36 Solum

37 Floor joists

38 Floorboards

39 Water tank

40 Hot water tank

Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

# 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

| Category 3   | Category 2  | Category 1                               |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

| $\hat{\mathcal{L}}$ | Structur | Structural movement  |  |  |  |
|---------------------|----------|--|--|--|--|
| Repair catego       | pry      | 1  |  |  |  |
| Notes               |          | At the time of our inspection there was no evidence of significant structural movement noted to affect the property within the limits of our inspection. |  |  |  |
| Dampne              |          | ess, rot and infestation   |  |  |  |
| Repair catego       | ory      | 1  |  |  |  |
| Notes               |          | There was no evidence found of significant dampness, rot or infestation within those areas of the property available for inspection.                     |  |  |  |
| Chimne              |          | y stacks   |  |  |  |
| Repair catego       | pry      | -  |  |  |  |
| Notes               |          | Not applicable.  |  |  |  |
| Roofing             |          | including roof space   |  |  |  |
| Repair category     |          | 1  |  |  |  |
| Notes               |          | The roof was noted to be in fair order commensurate with the age and type of property  |  |  |  |

| R               | Rainwater fittings   |  |  |  |
|-----------------|--|--|--|--|
| Repair category | 1  |  |  |  |
| Notes           | At the time of our inspection there was no evidence of damp staining/water staining on wall surfaces which would indicate leakage. It should be noted that it was not raining at the time of our inspection. |  |  |  |
| N               | ain walls  |  |  |  |
| Repair category | 1  |  |  |  |
| Notes           | The main outer walls of the property generally appeared in fair order consistent with age.   |  |  |  |
| H W             | indows, external doors and joinery   |  |  |  |
| Repair category | 1  |  |  |  |
| Notes           | These generally appeared in fair condition consistent with age.  |  |  |  |
| Ex              | ternal decorations   |  |  |  |
| Repair category | 1  |  |  |  |
| Notes           | No significant defects were noted.   |  |  |  |
| C               | onservatories / porches  |  |  |  |
| Repair category | -  |  |  |  |
| Notes           | Not applicable.  |  |  |  |
| C               | ommunal areas  |  |  |  |
| Repair category | -  |  |  |  |
| Notes           | Not applicable.  |  |  |  |

|                 | Garages and permanent outbuildings |  |  |
|-----------------|------------------------------------|--|--|
| Repair catego   | ory                                | 2  |  |
| Notes           |                                    | The outbuilding generally appears in fair condition consistent with age and usage.  We would note that the outbuilding is currently situated on communal ground and therefore may be required to be removed at a later date. |  |
| 2               | Outside                            | areas and boundaries   |  |
| Repair catego   | pry                                | 1  |  |
| Notes           |                                    | The boundaries appear reasonably well defined and are in adequate condition. Regular maintenance will be required. You should verify with your conveyancer the extent of the boundaries attaching to the property.           |  |
| Ceilings        |                                    |  |  |
| Repair catego   | ory                                | 1  |  |
| Notes           |                                    | Within the limits of our inspection these generally appeared in fair condition consistent with age.  |  |
| Internal        |                                    | walls  |  |
| Repair category |                                    | 1  |  |
| Notes           |                                    | The internal walls are largely covered with decorative finishes.   |  |
|                 |                                    | No defects noted.  |  |
| Floors in       |                                    | cluding sub-floors   |  |
| Repair category |                                    | 1  |  |

| Notes           |          | Flooring is generally level and firm to the tread.                              |  |  |
|-----------------|----------|---|--|--|
|                 |          | No access to the sub-floor chamber was possible at the time of our visit to the |  |  |
|                 |          | property. Within the limitations of our inspection there was no indication to   |  |  |
|                 |          | suggest significant defects in this area. It will, however be appreciated that  |  |  |
|                 |          | the area was not inspected and therefore no guarantees can be provided in       |  |  |
|                 |          | this regard.  |  |  |
| Internal        |          | joinery and kitchen fittings  |  |  |
| Repair catego   | ory      | 1   |  |  |
| Notes           |          | The internal joinery is generally in keeping with the age and type of           |  |  |
|                 |          | property and appeared in generally good condition consistent with age.          |  |  |
|                 |          | The kitchen units are of a modern type.   |  |  |
|                 | Chimney  | y breasts and fireplaces  |  |  |
| Repair catego   | ory      | -   |  |  |
| Notes           |          | Not applicable.   |  |  |
|                 | Internal | decorations   |  |  |
| Repair catego   | ory      | 1   |  |  |
| Notes           |          | The property is generally in fresh decoration throughout.                       |  |  |
| Cellars         |          |   |  |  |
| Repair category |          | -   |  |  |
| Notes           |          | Not applicable.   |  |  |
| Electrici       |          | ty  |  |  |
| Repair catego   | ory      | 1   |  |  |

| Notes                    | The electrical system within the property appeared of modern design, there being a circuit breaker type distribution board. It should be emphasised that the system was not tested at the time of our inspection. The Institution of Engineering and Technology recommends that inspections and testing are undertaken at least every ten years and on a change of occupancy. It should be appreciated that only the most recently constructed or re-wired properties will have installations which fully comply with IET regulations. |  |  |
|--------------------------|--|--|--|
| Gas                      |  |  |  |
| Repair category          | 1  |  |  |
| Notes                    | In the interest of safety all gas appliances should be checked by a Gas Safe Registered Engineer.  |  |  |
| Water, p                 | olumbing and bathroom fittings   |  |  |
| Repair category          | 1  |  |  |
| Notes                    | The plumbing and fittings appeared in serviceable condition but were not tested.   |  |  |
|                          | The sanitary fittings are of modern style and type.  |  |  |
| Heating                  | and hot water  |  |  |
| Repair category          | 1  |  |  |
| Notes                    | A gas fired central heating system has been installed. This will require ongoing and regular servicing.  |  |  |
|                          |  |  |  |
| Drainage                 | e<br>  |  |  |
| Drainage Repair category | <b>e</b>   |  |  |

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

| Structural movement                   | 1 |
|---------------------------------------|---|
| Dampness, rot and infestation         | 1 |
| Chimney stacks                        | - |
| Roofing including roof space          | 1 |
| Rainwater fittings                    | 1 |
| Main walls                            | 1 |
| Windows, external doors and joinery   | 1 |
| External decorations                  | 1 |
| Conservatories / porches              | - |
| Communal areas                        | - |
| Garages and permanent outbuildings    | 2 |
| Outside areas and boundaries          | 1 |
| Ceilings                              | 1 |
| Internal walls                        | 1 |
| Floors including sub-floors           | 1 |
| Internal joinery and kitchen fittings | 1 |
| Chimney breasts and fireplaces        | - |
| Internal decorations                  | 1 |
| Cellars                               | - |
| Electricity                           | 1 |
| Gas                                   | 1 |
| Water, plumbing and bathroom fittings | 1 |
| Heating and hot water                 | 1 |
| Drainage                              | 1 |

### Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

## 3. Accessibility information

### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

| 1. | Which floor (s) is the living accommodation on?                                     |     | First |    |   |
|----|---|-----|-------|----|---|
| 2. | Are there three steps or fewer to a main entrance to a property?                    | Yes | х     | No |   |
| 3. | Is there a lift to the main entrance door of the property?                          | Yes |       | No | х |
| 4. | Are all door openings greater than 750mm?   | Yes | х     | No |   |
| 5. | Is there a toilet on the same level as the living room and kitchen?                 | Yes | х     | No |   |
| 6. | Is there a toilet on the same level as a bedroom?                                   | Yes | х     | No |   |
| 7. | Are all rooms on the same level with no internal steps or stairs?                   | Yes | х     | No |   |
| 8. | Is there unrestricted parking within 25 metres of an entrance door to the building? | Yes | х     | No |   |

## 4. Valuation and conveyance issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated cost for insurance purposes.

### Matters for a solicitor or licensed conveyancer

We are unaware of any adverse planning proposals affecting the subjects although this should be confirmed by obtaining a Property Enquiry Certificate.

Absolute Ownership assumed. We are unaware of any easements, servitudes or rights of way which may adversely affect the property. This point should be confirmed by reference to the Title Deeds.

The subjects were constructed by Tulloch Homes, members of the NHBC scheme. It is assumed that the remainder of the 10 year NHBC guarantee will be transferred as a condition of sale.

The subjects form part of a block of flats and it has been assumed that maintenance/repair costs of the common parts of the building and external grounds will be shared on an equitable basis with the adjoining proprietors. It is therefore assumed that the costs of repairs detailed within this report which relate to these areas should be apportioned accordingly, although exact liability should be confirmed.

We understand that there is a monthly factoring charge payable which also includes for buildings insurance cover. This is understood to amount to approximately £25 per calendar month although would recommend that full details be confirmed in this regard.

Property market activity has been impacted due to the current response to Covid-19. This has resulted in an unprecedented set of circumstances on which to make a valuation judgement. The advice is therefore reported on the basis of "material valuation uncertainty" as per the RICS Red Book Global definition. Consequently, less certainty can be attached to the valuation than would otherwise be the case. It is recommended that the valuation of this property is kept under frequent review as more market evidence becomes available.

## Estimated reinstatement cost for insurance purposes

£145,000

We are of the opinion that the subjects should be insured for buildings reinstatement purposes for a sum of not less than £145,000.

### Valuation and market comments

### £172,000

Market Value assuming vacant possession is £172,000 (ONE HUNDRED AND SEVENTY TWO THOUSAND POUNDS STERLING).

Our valuation reflects current market conditions relating to this area. We would assume that current trends will prevail at the ultimate date of disposal with no adverse or onerous matters being introduced into the market during the intervening period which would have a detrimental effect on price.

| Report author  | Neil Cromarty  |  |
|----------------|--|--|
|                |  |  |
| Address        | 4 Ardross Street, INVERNESS. IV3 5NN.                          |  |
|                |  |  |
| Signed         | Neil Cromarty BAcc MRICS for and on behalf of Graham & Sibbald |  |
|                |  |  |
| Date of report | 8/9/2020   |  |

#### SINGLE SURVEY TERMS & CONDITIONS (WITH MVR)

#### **PART 1 – GENERAL**

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. \*

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this here: No

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

\* Which shall be in accordance with the current RICS Appraisal and Valuation Standards (The Red Book) and RICS Rules of Conduct.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to the 1<sup>st</sup> December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, A Single Survey is instructed by the seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisors without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisors of any of these.
- The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. \*\* The Transcript Mortgage Valuation report will be prepared from information contained in the report and the generic Mortgage Valuation Report.

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the Surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatsoever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

\*\* Which shall be in accordance with the current RICS Appraisal and Valuation Standards (The Red Book) and RICS Rules of Conduct.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a Surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is the estimated amount for which the Property should exchange, on the date of valuation, between a willing seller and a willing buyer in an arm's length transaction after proper marketing where the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in Part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm of company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 - DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an Independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey or properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property will be concise and will be restricted to matters that could have a material affect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report the following repair categories will be used to give an overall opinion of the state of repair and condition of the property:

2.3.1. **Category 3:** Urgent repairs or replacement are needed now.

Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

- 2.3.2. **Category 2:** Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3. **Category 1:** No immediate action or repair is needed.

#### **WARNING:**

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property which cannot be seen or accessed will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION & CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation within a willing buyer and willing seller in an arms-length transaction after proper marketing wherein the parties have each acted knowledgably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- \*There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- \*There are no particularly troublesome or unusual legal restrictions.
- \*There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis. Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a re-inspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

Valuation Certainty: Our valuation reflects market conditions for this area. For the purpose of this valuation it is assumed that this trend will continue. The result of the UK referendum to leave the EU has created uncertainty within the market, and it should be appreciated that the valuation is based on the most recent comparable evidence available.

# **Energy Performance Certificate (EPC)**

**Dwellings** 

# **Scotland**

#### 65 BROCK ROAD, INVERNESS, IV2 6HH

Dwelling type: Top-floor flat

Date of assessment: 03 September 2020

Date of certificate: 03 September 2020

Total floor area: 78 m<sup>2</sup>

Primary Energy Indicator: 116 kWh/m²/year

**Reference number:** 0878-1050-9231-6420-3220 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

**Main heating and fuel:** Boiler and radiators, mains

gas


#### You can use this document to:

Compare current ratings of properties to see which are more energy efficient and environmentally friendly

# Estimated energy costs for your home for 3 years\*

£1,305

 $^st$  based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (81)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



# Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band B (84)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element               | Description                                 | Energy Efficiency | Environmental |
|-----------------------|---|-------------------|---------------|
| Walls                 | Timber frame, as built, insulated (assumed) | ****              | ****          |
| Roof                  | Pitched, 300 mm loft insulation             | ****              | ****          |
| Floor                 | (another dwelling below)                    | _                 | _             |
| Windows               | Fully double glazed                         | ****              | <b>★★★</b> ☆  |
| Main heating          | Boiler and radiators, mains gas             | <b>★★★★☆</b>      | <b>★★★</b> ☆  |
| Main heating controls | Programmer, TRVs and bypass                 | <b>★★★☆☆</b>      | <b>★★★☆☆</b>  |
| Secondary heating     | None  | _                 | _             |
| Hot water             | From main system                            | <b>★★★★☆</b>      | <b>★★★★</b> ☆ |
| Lighting              | Low energy lighting in all fixed outlets    | ****              | ****          |

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

# The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 20 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 1.6 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

## Estimated energy costs for this home

|           | Current energy costs | Potential energy costs | Potential future savings |  |
|-----------|----------------------|------------------------|--------------------------|--|
| Heating   | £858 over 3 years    | £858 over 3 years      | N                        |  |
| Hot water | £237 over 3 years    | £237 over 3 years      |                          |  |
| Lighting  | £210 over 3 years    | £210 over 3 years      | Not applicable           |  |
| Totals    | £1,305               | £1,305                 |                          |  |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

## **Recommendations for improvement**

None

### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

| Heat demand                  | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 3,398             | N/A                       | N/A                              | N/A                             |
| Water heating (kWh per year) | 1,767             |                           |                                  |                                 |

### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:
Assessor membership number:
Company name/trading name:
Address:

Mr. Neil Cromarty
EES/009427
Graham & Sibbald
4 Ardross Street
Inverness

IV3 5NN

Phone number: 01463 236977
Email address: inverness@g-s.co.uk
Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

| 65 Brock Road  |
|----------------|
| Milton of Leys |
| Inverness      |
| IV2 6HH        |
|                |
|                |
|                |

| Seller(s) | Karex Weetheredk |
|-----------|------------------|
|           | XHRRAKAKAKAK     |

| Completion date of property | 02/09/2020 |
|-----------------------------|------------|
| questionnaire               |            |

# **GRAHAM + SIBBALD**

### **Note for sellers**

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

# Information to be given to prospective buyer(s)

| 1. | Length of ownership  |    |  |
|----|--|----|--|
|    | How long have you owned the property? 3 years 2 months   |    |  |
| 2. | Council tax  |    |  |
|    | Which Council Tax band is your property in?  |    |  |
| 3. | Parking  |    |  |
|    | What are the arrangements for parking at your property?  (Please tick all that apply)      Garage      Allocated parking space      Driveway      Shared parking      On street      Resident permit      Metered parking      Other (please specify): |    |  |
| 4. | Conservation area  |    |  |
|    | Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?   | No |  |

| 5. | Listed buildings  |                          |
|----|---|--------------------------|
|    | Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?                        | No                       |
| 6. | Alterations/additions/extensions  |                          |
| а. | (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? |                          |
|    | If you have answered yes, please describe below the changes which you have made:  | No                       |
|    | (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?   |                          |
|    | If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.                             |                          |
|    | If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:                                      |                          |
| b. | Have you had replacement windows, doors, patio doors or double glazing installed in your property?  | No                       |
|    | If you have answered yes, please answer the three questions below:  |                          |
|    | (i) Were the replacements the same shape and type as the ones you replaced?   |                          |
|    | (ii) Did this work involve any changes to the window or door openings?  |                          |
|    | (iii) Please describe the changes made to the windows doors, or approximate dates when the work was completed):   | patio doors (with        |
|    | Please give any guarantees which you received for this work to yagent.  | your solicitor or estate |

| 7. | Central heating  |                     |
|----|--|---------------------|
| a. | Is there a central heating system in your property?  |                     |
|    | (Note: a partial central heating system is one which does not heat all the main rooms of the property —    | Yes                 |
|    | the main living room, the bedroom(s), the hall and the bathroom).  |                     |
|    | If you have answered yes or partial – what kind of central heating is there?                               |                     |
|    | (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).                                 |                     |
|    | Gas fired  |                     |
|    | If you have answered yes, please answer the three questions below:   |                     |
|    | (i) When was your central heating system or partial central heating  June 2017 (at build)                  | g system installed? |
|    | (ii) Do you have a maintenance contract for the central heating system?                                    | Yes                 |
|    | If you have answered yes, please give details of the company with which you have a maintenance contract:   |                     |
|    | British Gas  |                     |
|    | (iii) When was your maintenance agreement last renewed? (Please and year).                                 | provide the month   |
|    | May 2020   |                     |
| 8. | Energy Performance Certificate   |                     |
|    | Does your property have an Energy Performance Certificate which is less than 10 years old?                 | Yes                 |
| 9. | Issues that may have affected your property  |                     |
| а. | Has there been any storm, flood, fire or other structural damage to your property while you have owned it? | No                  |
|    | If you have answered yes, is the damage the subject of any outstanding insurance claim?                    |                     |
| b. | Are you aware of the existence of asbestos in your property?   | No                  |
|    | If you have answered yes, please give details:   |                     |

### 10. Services

a. Please tick which services are connected to your property and give details of the supplier:

| Services                                  | Connected | Supplier       |
|---|-----------|----------------|
| Gas or liquid<br>petroleum<br>gas         | Yes       | Bulb           |
| Water mains<br>or private<br>water supply | Yes       | Scottish Water |
| Electricity                               | Yes       | Bulb           |
| Mains<br>drainage                         | Yes       | Scottish Water |
| Telephone                                 | Yes       | ВТ             |
| Cable TV or satellite                     | Yes       | Sky            |
| Broadband                                 | Yes       | ВТ             |

| b. | Is there a septic tank system at your property?  | No |
|----|--|----|
|    | If you have answered yes, please answer the two questions below:   |    |
|    | (iv) Do you have appropriate consents for the discharge from your septic tank?   |    |
|    | (v) Do you have a maintenance contract for your septic tank?  If you have answered yes, please give details of the company with which you have a maintenance contract: |    |

| 11. | Responsibilities for shared or common areas   |            |
|-----|---|------------|
| a.  | Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?   | Don't Know |
|     | If you have answered yes, please give details:  |            |
| b.  | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?  | Yes        |
|     | If you have answered yes, please give details:  |            |
|     | Cottage flat  |            |
| C.  | Has there been any major repair or replacement of any part of the roof during the time you have owned the property?   | No         |
| d.  | Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?   | Yes        |
|     | If you have answered yes, please give details:  |            |
|     | Common area   |            |
| e.  | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?   | Yes        |
|     | If you have answered yes, please give details:  |            |
|     | Common area.  |            |
| f.  | As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.) | No         |
|     | If you have answered yes, please give details:  |            |
| 12. | Charges associated with your property   |            |
| a.  | Is there a factor or property manager for your property?  | Yes        |
|     | If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:  |            |
|     | First Port  |            |

| b.  | Is there a common buildings insurance policy?   | Yes |
|-----|---|-----|
|     | If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?  | Yes |
| c.  | Please give details of any other charges you have to upkeep of common areas or repair works, for exam maintenance or stair fund.  |     |
| 13. | Specialist works  |     |
| a.  | As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?   | No  |
|     | If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.   |     |
| b.  | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?  If you have answered yes, please give details:  | No  |
| c.  | If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?  If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. |     |
|     | Guarantees are held by:   |     |

| 14.         | Guarantees   |                  |             |
|-------------|--|------------------|-------------|
| a.          | Are there any guarantees or warranties for any of the following:                                       |                  |             |
| <i>(</i> ;) | Electrical work  | With Title D     |             |
| (i)         |  |                  |             |
| (ii)        | Roofing  | With Title D     | eeas        |
| (iii)       | Central heating  | With Title D     | eeds        |
| (iv)        | National House Building Council (NHBC)   | With Title D     | eeds        |
| (v)         | Damp course  | With Title Deeds |             |
| (vi)        | Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy) | No               |             |
| b.          | If you have answered 'yes' or 'with title do installations to which the guarantee(s) rel               |                  | the work or |
| c.          | Are there any outstanding claims under any of the guarantees listed above?                             |                  | No          |
|             | If you have answered yes, please give de   | tails:           |             |
| 15.         | Boundaries   |                  |             |
|             | So far as you are aware, has any boundary of your property been moved in the last 10 years?            |                  | No          |
|             | If you have answered yes, please give det  | tails:           |             |
|             |  |                  |             |

| 16. | Notices that affect your property   |    |  |
|-----|---|----|--|
|     | In the past three years have you ever received a notice:  |    |  |
| a.  | advising that the owner of a neighbouring property has made a planning application?   | No |  |
| b.  | that affects your property in some other way?   | No |  |
| c.  | that requires you to do any maintenance, repairs or improvements to your property?  | No |  |
|     | If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property. |    |  |

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

| I ACCEPT 🗹 |
|------------|
|------------|

Date: 02/09/2020

# **Mortgage Valuation Report for Home Report**



| Source: G+S Home Report   | Seller Name  | XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX | Reference                      | INV-2020\08\0145                               |
|---|--|---|--------------------------------|--|
| Area  |  | Postcode IV2 6HH                        |                                |  |
| 2) Description of property Property Type Flat Year Built 2017   | House Type Purp  Non Traditional Co  (*Specify under get | onstruction? No                         |                                | oct property 1  ors in block 2  ots in block 4 |
| 3) Accommodation - give number of:  Receptions 1 Bedrooms 2  Other None. Garage   | Kitchens 1   | Bathrooms 2 Outbuildings None           | Total Inside 2<br>W.C.s Garden | No of floors 1                                 |
| 4) Tenure Absolute Ownership  Any known or reported problems with   |  | rears unexpired:                        | rges?                          |  |
| Owner occupied x Tenanted  If part tenanted, please give details  | Vacant   |   |                                |  |
| 5) Subsidence, Settlement and Landsli  Does the property show signs of, or is subject to landslip, heave, settlement lf yes, please clarify | s the property located nea                               | , INO                                   |                                |  |
| Are essential ex<br>Should the repairs be effected befo   | etention recommended?                                    | ida furthar datail:                     | Ye:<br>Ye:<br>Ye:              | No x   |
| The answer to any of the above ques   | niona ia ita, piease piovi                               | ide future detail.                      |                                |  |



|  |   |   | 4                                  |  |
|--|---|---|------------------------------------|--|
| 7) Services Main   | s water x Mains drainage x Ele  | ectricity x Gas x Central he              | eating Gas                         |  |
| 8) Insurance Reinst  | catement Value oors measured internally (m²)  |   | 78                                 |  |
|  | inc. demolition, site clearance, profess  | sional fees.local authority require       | ements                             |  |
|  | g (inc all other structures within the site   | · · · · · · · · · · · · · · · · · · ·     | + 1/15 (101)                       |  |
|  | n for Mortgage Purposes (Assuming Vad the property as suitable security for a   |   |                                    |  |
| If no, please provi  | de reasons:   |   |                                    |  |
|  |   |   |                                    |  |
|  |   |   |                                    |  |
| If Yes, please prov  | ide your valuation  |   |                                    |  |
| Valuation in prese   | nt condition:   |   | £172,000                           |  |
| Valuation on com   | oletion of any works required under Qu  | restion 6                                 |                                    |  |
| 10) General Comm   |   | Vor the location, which affects the       | proporty                           |  |
| Please advise of any special features of the property and/or the location, which affects the property.  The property comprises a self-contained first floor flat within a two storey semi-detached block of similar apartments. The main outer walls are of modern cavity construction comprising a structural timber frame inner leaf and roughcasted concrete block outerleaf. The roof is of pitched design and clad with concrete tiles. |   |   |                                    |  |
| Leys area lying on   | part of a modern private residential de<br>the southern side of Inverness city cen<br>age and type, whilst all main facilities                      | tre. Immediate surrounding prope          | erties comprise dwellings of a     |  |
|  | pection the property was found to be in<br>te repairs recommended as a condition  |   | tained condition and with there    |  |
| Property Enquiry Co  | of any adverse planning proposals affeo<br>ertificate. Absolute Ownership assume<br>ely affect the property. This point shou                        | d. We are unaware of any easeme           | ents, servitudes or rights of way  |  |
| · · · · · · · · · · · · · · · · · · ·  | constructed by Tulloch Homes, membe<br>tee will be transferred as a condition o   |   | med that the remainder of the 10   |  |
| building and exter   | part of a block of flats and it has been<br>rnal grounds will be shared on an equi<br>epairs detailed within this report which<br>uld be confirmed. | table basis with the adjoining pro        | prietors. It is therefore assumed  |  |
|  | at there is a monthly factoring charge p<br>ount to approximately £25 per calendar  |   |                                    |  |
| In our opinion the   | property forms suitable security for loa  | an purposes subject to specific ler       | nders criteria which may vary.     |  |
|  |   |   |                                    |  |
|  | IS A CONFIDENTIAL REPORT PREPARED personally inspected the property desc  |   | te professional indemnity cover is |  |
| neiu.  |   | Company / Firm Name Gr                    | aham ± Cihhald                     |  |
|  |   | Company / Firm Name Gra<br>Office Name In |                                    |  |
|  | 1//   |   |                                    |  |
| Signature  | 10011   | Office Addr3                              | Ardross Street                     |  |
|  | Neil Cromarty BAcc MRICS<br>for and on behalf of Graham & Sibbald   | Office Addr2                              |                                    |  |
| 1  |   | Area                                      |                                    |  |

Date of inspection 03/09/2020 Town Inverness 08/09/2020 Date of report Postcode IV3 5NN Tel no 01463 236977

#### MORTGAGE VALUATION- CONDITIONS OF ENGAGEMENT



A valuation for mortgage is a limited inspection and report produced for Building Societies, Banks and other Lenders to enable them to make a lending decision. IT IS NOT A SURVEY. Unless otherwise stated the date of valuation will be the date of inspection.

This report is used to guide the lender on the market value of the property for mortgage purposes, and is carried out for this purpose alone. Although the inspection will be carried out by a valuer who will usually be a qualified surveyor it is not a detailed inspection of the property, and only major visible defects will be noted. Subject to reasonable accessibility, the roof space is inspected only to the extent visible from the access hatch without entering it. The surveyor will not inspect under floor areas, communal roof space or other parts not readily accessible. The exterior and roof of the property will be inspected from ground level only from within the boundaries of the site and adjacent/communal public areas. The area of the property will be taken into account, and the rooms individually inspected, but floor coverings and furniture will not be moved. Services (such as water, gas, electricity and drainage) will not be tested and we will not advise as to whether these comply with regulations in respect of these services.

The surveyor may recommend that a part of the mortgage be retained by the lenders until such time as particular repair works are carried out. Similarly the report may suggest that the borrower should undertake to carry out certain repairs or commission more extensive investigation where hidden defects are suspected since these may have a material effect on the value of the property. If a retention is recommended then the figure should not be regarded as an estimate of repair costs. Its purpose is to protect the interests of the lending institution. It is recommended that detailed estimates be obtained before proceeding with the purchase. Attention is drawn to the fact that if a subsequent transcription of this report is prepared on a lenders form, then in order to comply with the lenders specific requirements, the wording or phraseology may differ. Many people rely on the Mortgage Valuation Certificate in the mistaken belief that it is a detailed survey. The report is often made available to house buyers by lenders, but this does not mean that it should be relied upon as a report of the condition of the building.

The definition of "market value" is the estimated amount for which a property should exchange on the date of valuation, between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had acted knowledgeably, prudently and without compulsion. For the purpose of this market value the surveyor has assumed that vacant possession will be provided. Unless otherwise stated the surveyor has valued the interest on a Comparable Basis.

The inspection that has been undertaken should not be regarded as a survey. The surveyor did not inspect parts of the property which were covered, unexposed or inaccessible and are therefore unable to report that any such part of the property is free from defect. Defects which are not considered materially to affect the value of the property or other matters which would be attended to during maintenance, may not have been mentioned. If defects have been mentioned in this report, they should be regarded as indicative and not exhaustive. For the purposes of this valuation the surveyor assumes that all uninspected areas are free from defect which would have a material effect on value.

In accordance with our normal practice, we must state that this report is for the use only of the party to whom it is addressed or their named client and no responsibility is accepted to any third party for the whole or any part of its content. In addition, we would bring to your attention that neither the whole nor any part of this report, nor any reference thereto, may be included in any document, circular or statement without prior written approval of the form and context in which it will appear.

The surveyor shall, unless otherwise expressly agreed, rely upon information provided by the Client and/or the Client's legal or other professional advisers relating to tenure, leases and all other relevant matters.

For the purposes of this valuation the surveyor has assumed that all ground burdens are nominal or have been redeemed and that there are no unusual outgoings or onerous restrictions contained within the Titles of which we have no knowledge. The surveyor has further assume that the subjects are unaffected by any adverse planning proposals.

Unless otherwise stated, it is assumed that all the required valid planning permissions and statutory approvals for the building and for their use, including any recent or significant extensions or alterations, have been obtained and complied with. It has been further assumed that no deleterious or hazardous materials or techniques have been used in the construction of the subject and that there is no contamination in or from the ground or from the immediate surrounds.

The surveyor will not carry out an asbestos inspection and will not be acting as an asbestos inspector in completing a valuation inspection of properties that may fall within the Control of Asbestos Regulations 2012. No enquiry of the duty holder, as defined in the Control of Asbestos Regulations 2012, of the existence of an asbestos register, or of any plan for the management of asbestos will be made. Your legal adviser/conveyancer should confirm the duty holder under these regulations, the availability of an Asbestos Register and the existence and management of any asbestos containing materials. For the purposes of this valuation, the surveyor has assumed that there is a duty holder, as defined in the Control of Asbestos Regulations 2012, and that a Register of Asbestos and effective Management Plan is in place which does not require any immediate expenditure or pose a significant risk to health or breach the HSE Regulations.

The surveyor confirms that this mortgage valuation is prepared in accordance with the RICS Valuation - Global Standards 2017 and incorporating IVSC International Valuation Standards and, unless other stated, we are External Valuers as defined therein. Further information may also be obtained from the Royal Institution of Chartered Surveyors in Scotland, 3rd Floor, 125 Princes Street, Edinburgh EH2 4AD. Tel no 0131 225 7078.

As part of this remit, the surveyor may, where he/she feels qualified and experienced to do so, provide general comment on standard appropriate supplementary documentation, presented to us by the clients lender and conveyancer. In the event of a significant amount of documentation being provided to us, an additional fee may be incurred. Any additional fees will be agreed.

We confirm this firm operates formal procedures to deal with complaints from clients in accordance with Bye-law 19 Regulation 2.7 of the Royal Institution of Chartered Surveyors Rules of Conduct and Disciplinary Procedures. A copy of this procedure is available on request.

Date: 19/02/2016